This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


A DEADERA

Inventor: Rogers et al.
Docket No.: 2316.1497US01
Title: Method and Apparatus for Inspecting End Surfaces on Optical Connectors
Serial No.: 09/892,192
Sheet 1 of 6




BADENS

Inventor: Rogers et al.
Docket No.: 2316.1497US01
Title: Method and Apparatus for Inspecting End Surfaces on Optical Connectors
Serial No.: 09/892,192
Sheet 2 of 6




BANELINE

Inventor: Rogers et al.
Docket No.: 2316.1497US01
Title: Method and Apparatus for Inspecting End Surfaces on Optical Connectors
Serial No.: 09/892,192
Sheet 3 of 6





Inventor: Rogers et al.
Docket No.: 2316.1497US01
Title: Method and Apparatus for Inspecting End Surfaces on Optical Connectors
Serial No.: 09/892,192
Sheet 4 of 6





Inventor: Rogers et al.
Docket No.: 2316.1497US01
Title: Method and Apparatus for Inspecting End Surfaces on Optical Connectors
Serial No.: 09/892,192
Sheet 5 of 6

FIG.5

